

# MILLTEK

<b>SYSTEM NO.</b>	SSXAU1023
<b>DESCRIPTION</b>	Particulate Filter-back
<b>NOTES</b>	

## PARTS REQUIRED

PART NO.	DESCRIPTION	QUANTITY	IN PACKAGE
<b>F5156</b>	<b>Adapter to OE Downpipe</b>	<b>1</b>	
CHC68SS	68mm Band Clamp - 304 S/S	1	
<b>MSAU793REP</b>	<b>Centre Connecting Pipe</b>	<b>1</b>	
CHC83SS	83mm Band Clamp - 304 S/S	1	
F20050	5.0mm Spacer	2	
<b>MSAU809</b>	<b>Inner Tailpipes</b>	<b>2</b>	
CHC66.5SS	66.5mm Band Clamp-304 S/Steel	2	
<b>MSAU810</b>	<b>LH Valved Outlet Pipe</b>	<b>1</b>	
CHC66.5SS	66.5mm Band Clamp-304 S/Steel	1	
F3160	Wire Formed Spring Assembly	1	
<b>MSAU811</b>	<b>RH Valved Outlet Pipe</b>	<b>1</b>	
CHC66.5SS	66.5mm Band Clamp-304 S/Steel	1	
F3160	Wire Formed Spring Assembly	1	
<b>MSAU812</b>	<b>Tailpipe Extensions</b>	<b>4</b>	
CHC66.5SS	66.5mm Band Clamp-304 S/Steel	4	
<b>MSTIP244</b>	<b>Carbon Fibre 4.5" Trims</b>	<b>4</b>	
CHC66.5SS	66.5mm Band Clamp-304 S/Steel	4	
<b>MSVAG31</b>	<b>Race Rear Silencer</b>	<b>1</b>	
CHC83SS	83mm Band Clamp - 304 S/S	1	

# MILLTEK

## TECHNICAL INFORMATION

NOTES

OE rear silencer hanger brackets need to be rotated 180° as per below images:

OE Position:



Rotated 180°:

